

Adjusting the speed of the saw bar

Lowering the speed = turn the valve in (clockwise).

Raise the speed = turn the valve out (counter clockwise).

When turning the valve inward, the oil to the cylinder is restricted which slows down the saw bar.

NOTE!

If the saw bar comes out too fast, reduce the speed to prevent damage to the saw motor.

